DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

69.12 File #:

DAILY PROJECT JOURNAL

Prime Contractor: American Bridge/Fluor Enterprises, a JV Report No: DPJ-000571 Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Dated: **Contractor:** 02-Jan-2008

Location: Changxing Island, Shanghai, China

Submittals(New / Total): CWR's: / HSR's: / NCR's: / **Item** Title **Detail** 1 I reviewed and approved transmittal TL-08-0001, which contains HSR(B) – Heat Straightening Requests (HSRs) 027 Rev. 0. 2 Critical Weld Repairs (CWRs) I reviewed and approved transmittal TL-08-0006, which contains B-CWR 013 Rev. 0. 3 I reviewed the transmittals TL-07-0964, TL-07-0965, TL-07-0966, Heat Straightening Requests (HSRs) TL-07-0967, TL-07-0968 and TL-07-0969, which contain the closes of HSR(B) – 009 Rev. 0, HSR(B) – 010 Rev. 0, HSR(B) – 011 Rev. 0, HSR(B) -012 Rev. 0, HSR(B) -013 Rev. 0 and HSR(B) -014 Rev. 0, respectively. I had a discussion with ABF Nate L. regarding the ambiguous statements in the transmittals and distortions after heat straightening. ABF Nate L. stated that he would talk to ZPMC to clarify. Without further information, the transmittals are pending for decisions. 4 I talked to ABF Mr. Gang Jiao regarding the distortion corrective action(s) Key conversations ABF / ZPMC would propose for controlling the distortion caused by the welding of open ribs to side plate. ABF Gang Jiao stated that ABF / ZPMC would submit a revision of HSR (B) – 021 Rev. 0, which will contain the new proposed corrective action(s). 5 Other important observations I continued working on the report of OBG closed rib weld trial #2 macro-etching tests with Mr. Peter D. **Inspected By:** Liu, Chengwen Quality Assurance Inspector

Reviewed By: Lowry, Patrick **QA** Reviewer